L Number	Hits	Search Text	DB	Time stamp
Number 1	120	Huber near robert.inv.	USPAT;	2003/09/22
*	.20	Trabel fied Tobelliffy	US-PGPUB;	11:54
			EPO; JPO;	11.54
			DERWENT;	
			IBM_TDB	
3	3	Huber near robert .inv. and 29/\$.ccls.	USPAT;	2003/09/22
	J	induct fied Tobett filly, and 29/9.ccis.	US-PGPUB;	
		,		11:55
			EPO; JPO;	
			DERWENT;	
2	3	Huber ween select income and accombined	IBM_TDB	0000100100
2	3	Huber near robert .inv. and assembly near	USPAT;	2003/09/22
İ		line	US-PGPUB;	11:55
			EPO; JPO;	
			DERWENT;	
	_		IBM_TDB	
-	2	5528826.pn.	USPAT;	2003/09/18
		· ·	US-PGPUB;	06:06
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	2	4667403.pn.	USPAT;	2003/09/18
			US-PGPUB;	06:08
1			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	6	("Re25894" "3264918" "3954542"	USPAT	2003/09/18
		"4128174" "4348276" "4498232").PN.		06:07
-	54	pcb and conveyor and mounting and	USPAT;	2003/09/18
		scanner	US-PGPUB;	06:11
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	0	bad adj mark near scanner and asembly and	USPAT;	2003/09/18
		system	US-PGPUB;	06:12
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
_	3	bad adj mark near scanner	USPAT;	2003/09/18
	•	and the state of t	US-PGPUB;	06:13
			EPO; JPO;	30.13
			1	
			DERWENT;	
_	18	coannor and nick and nices and I AM and	IBM_TDB	2002/00/42
-	15	scanner and pick and place and LAN and	USPAT;	2003/09/18
		PCB	US-PGPUB;	06:14
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	

_	1164	scanner and PCB	USPAT;	2003/09/18
-	1104	scanner and PCB	•	2003/09/18 06:15
			US-PGPUB;	06:15
			EPO; JPO;	
	ŧ		DERWENT;	
	_	DOD I	IBM_TDB	2000/00/40
-	1	scanner and PCB and mounting near	USPAT;	2003/09/18
	1	machine	US-PGPUB;	06:15
		·	EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	38	scanner and PCB and mounting and	USPAT;	2003/09/18
		conveying	US-PGPUB;	06:17
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	409	PCB and assembly near line	USPAT;	2003/09/18
			US-PGPUB;	06:21
	}		EPO; JPO;	
	1		DERWENT;	
			IBM_TDB	
-	52	PCB and assembly near line and scanner	USPAT;	2003/09/21
		and detect	US-PGPUB;	10:37
			EPO; JPO;	
			DERWENT:	
			IBM_TDB	
-	16	circuit near panel and scanner and	USPAT;	2003/09/18
		conveyor	US-PGPUB;	06:33
		-	EPO; JPO;	
			DERWENT;	
			IBM_TDB	
_	o	20020143423.URPN.	USPAT	2003/09/18
				06:25
_	4	("4496971" "5157762" "5663569"	USPAT	2003/09/18
		"5697699").PN.		06:28
	2	("4978224" "4982105").PN.	USPAT	2003/09/18
	_	, , , , , , , , , , , , , , , , , , , ,		06:29
-	4	("4578810" "4692690" "4728195"	USPAT	2003/09/18
		"4799175").PN.		06:30
-	90	Defective near circuit and scanning same	USPAT;	2003/09/18
		device	US-PGPUB;	06:43
			EPO; JPO;	33170
			DERWENT;	
			IBM_TDB	
_	11	scanning near pcb and mounting	USPAT;	2003/09/18
			US-PGPUB;	06:54
			EPO; JPO;	UU:34
			DERWENT;	
			•	
L	L	L	IBM_TDB	1

•	21	("3052339" "3100039" "3522942"	USPAT	2003/09/18
		"3680677" "4274529" "4301958"		06:46
		"4730526" "4747477" "4846623"		
		"4962841" "5084829" "5125497"		
		"5165516" "5222585" "5352085"		
		"5366212" "5441380" "5533861"		
		"5588797" "5609236" "5626238").PN.		
-	13	("2980252" "3372804" "3637066"	USPAT	2003/09/18
		"4254877" "4411366" "4830195"		06:49
		"5022532" "5197585" "5267654"		
		"5280838" "5294004" "5306877"		
		"5307921").PN.		
-	27	4301958.URPN.	USPAT	2003/09/18
				06:50
_	4	("3946931" "3973713" "4301958"	USPAT	2003/09/18
		"4526646").PN.		06:53
-	6	("3444612" "3522942" "4027246"	USPAT	2003/09/18
•		"4030622" "4054238" "4144960").PN.		06:54
•	1	scanning near pcb and mounting	JPO;	2003/09/18
			DERWENT;	06:55
			IBM_TDB	
-	9	scanning near pcb	JPO;	2003/09/18
			DERWENT;	06:59
			IBM_TDB	
_	1	2002-370272.NRAN.	DERWENT	2003/09/18
				06:55
_	1	1993-400771.NRAN.	DERWENT	2003/09/18
				06:57
-	1	1991-025429.NRAN.	DERWENT	2003/09/18
				06:57
_	0	bad adj mark near scanner and pcb	JPO;	2003/09/18
		•	DERWENT;	07:00
			IBM_TDB	
-	1	bad adj mark near scanner and panel	JPO;	2003/09/18
		•	DERWENT;	07:00
			IBM_TDB	
-	1533	scanner and panel	JPO;	2003/09/18
		-	DERWENT;	07:09
			IBM_TDB	
•	3	scanner and circuit near panel	JPO;	2003/09/18
		·	DERWENT;	07:00
			IBM_TDB	
-	0	scanner and panel and process and pcb	JPO;	2003/09/18
			DERWENT;	07:01
			IBM_TDB	
-	11	scanner and pcb same method	JPO;	2003/09/18
		•	DERWENT;	07:03
			IBM_TDB	
-	14	detecting and scanner and pcb	JPO;	2003/09/18
			DERWENT;	07:05
			IBM_TDB	
		<u> </u>		

-	0	detecting and scanner and mounting near	JPO;	2003/09/18
		machine	DERWENT;	07:05
			IBM_TDB	
•	9	scanner and mounting near machine	JPO;	2003/09/18
			DERWENT;	07:05
			IBM_TDB	
-	0	9307447.URPN.	USPAT	2003/09/18
				07:08
-	0	scanner and panel and testing and marking	JPO;	2003/09/18
			DERWENT;	07:09
			IBM_TDB	
-	43	scanner and panel and mounting	JPO;	2003/09/18
			DERWENT;	07:10
			IBM_TDB	
•	1	scanner and PCB and inspecting and	JPO;	2003/09/18
		processing	DERWENT;	07:12
			IBM_TDB	
-	1	1989-311278.NRAN.	DERWENT	2003/09/18
				07:11
-	11	scanner and PCB and inspecting	JPO;	2003/09/18
			DERWENT;	07:13
			IBM_TDB	
-	0	scanner and PCB adj assembly near line	JPO;	2003/09/18
			DERWENT;	07:13
			IBM_TDB	
-	1	scanner and PCB adj assembly near line	USPAT;	2003/09/18
			US-PGPUB;	07:15
	:		EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	7	("4459663" "4847761" "5119307"	USPAT	2003/09/18
		"5197001" "5307261" "5796614"		07:14
		"5838965").PN.		
-	9	scanner and PCB adj mounting and	USPAT;	2003/09/18
		assembly	US-PGPUB;	07:16
			EPO; JPO;	
			DERWENT;	
_	424384	scanner and bad near mark and PCBand	IBM_TDB	2002/00/40
-	424384		USPAT;	2003/09/18
		mounting and assembly	US-PGPUB;	07:17
			EPO; JPO;	
			DERWENT;	
_	0	coonney and had year made and DOD	IBM_TDB	2002/20/40
•	U	scanner and bad near mark and PCB and	USPAT;	2003/09/18
		mounting and assembly	US-PGPUB;	07:17
			EPO; JPO;	
			DERWENT;	
_	0	scanner and bad near mark and PCB and	IBM_TDB	2002/00/40
-		mounting	USPAT;	2003/09/18
			US-PGPUB;	07:17
			EPO; JPO; DERWENT;	
			IBM_TDB	
		2 44.56.20 AM Dogg 4	םמו_וויטו	<u> </u>

•	0	scanner and bad near mark and PCB	USPAT;	2003/09/18
			US-PGPUB;	07:17
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	2	scanner and PCB and component near	USPAT;	2003/09/18
		placement and conveyor	US-PGPUB;	07:18
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	14	("4650333" "4677302" "5088828"	USPAT	2003/09/18
		"5200799" "5329359" "5444537"		07:19
		"5450204" "5465152" "5780866"		
		"5822449" "5862973" "5902353"		
		"5903353" "6005669").PN.		
-	9	("4894790" "4953100" "4978224"	USPAT	2003/09/18
		"5046113" "5058178" "5086477"		07:20
		"5134575" "5134665" "5245671").PN.		
-	36	motor near core and stack and apparatus	USPAT;	2003/09/18
		and 29/\$.ccls.	US-PGPUB;	07:38
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	2208	transformer and 29/\$.ccls.	USPAT;	2003/09/18
			US-PGPUB;	07:39
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	97	transformer near assembly and 29/\$.ccls.	USPAT;	2003/09/18
			US-PGPUB;	07:41
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	0	magnetor and 29/\$.ccls.	USPAT;	2003/09/18
			US-PGPUB;	07:42
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	36066	magnetoresistornear element and 29/\$.ccls.	USPAT;	2003/09/18
			US-PGPUB;	07:42
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	6	magnetoresistor near element and	USPAT;	2003/09/18
		29/\$.ccis.	US-PGPUB;	07:43
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	2074	fluid near containment	USPAT;	2003/09/21
			US-PGPUB;	08:42
			EPO; JPO;	
1			DERWENT;	
	L		IBM_TDB	

Search History 9/22/03 11:56:20 AM Page 5

			T	
-	0	fluid near containment and gasket and	USPAT;	2003/09/21
]	substrate and dianostic	US-PGPUB;	08:43
	•		EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	3	fluid near containment and gasket and	USPAT;	2003/09/21
		substrate and diagnostic	US-PGPUB;	08:44
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	0	fluid near containment and gasket and	USPAT;	2003/09/21
		substrate and biomolecular near array	US-PGPUB;	08:44
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	0	fluid near containment and biomolecular	USPAT;	2003/09/21
		near array	US-PGPUB;	08:44
			EPO; JPO;	,
			DERWENT;	
			IBM_TDB	
-	27	fluid near containment and rna	USPAT;	2003/09/21
			US-PGPUB;	08:56
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
_	6717609	wire near holding device	USPAT;	2003/09/21
		3	US-PGPUB;	08:57
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
_	2	wires adj holding near device and	USPAT;	2003/09/21
	_	29/596.ccls.	US-PGPUB;	08:57
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	0	JP11040999.pn.	USPAT;	2003/09/21
			US-PGPUB;	09:29
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
_	156855	Yamamoto.inv.	USPAT;	2003/09/21
	1		US-PGPUB;	09:29
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
1.	0	Yamamoto .inv. and scanner and PCB	USPAT;	2003/09/21
-	0	i amamoto inivi and stainer and Fob	US-PGPUB;	09:30
			EPO; JPO;	33.00
			DERWENT;	
			IBM_TDB	
			IDIN_IDD	

	1075	Yamamoto .inv. and scanner	USPAT;	2003/09/21
	10/3	Tamamoto imv. and scanner	US-PGPUB;	09:30
			EPO; JPO;	09:30
			DERWENT;	
			1	
	60	V	IBM_TDB	0000/00/04
-	62	Yamamoto .inv. and scanner and mounting	USPAT;	2003/09/21
			US-PGPUB;	09:33
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	141	Yamamoto .inv. and scanner and panel	USPAT;	2003/09/21
			US-PGPUB;	09:43
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	0	Yamamoto adj et near al .inv. and scanner	USPAT;	2003/09/21
		and panel	US-PGPUB;	09:43
		•	EPO; JPO;	
			DERWENT;	
			IBM_TDB	
_	0	Yamamoto adj et near al .inv. and scanner	USPAT;	2003/09/21
		Talliano au Ot noan an inno ana obanno	US-PGPUB;	09:43
			EPO; JPO;	00.40
			DERWENT;	
			IBM_TDB	
	5	Yamamoto .inv. and scanner and machine	USPAT;	2003/09/21
-	3		US-PGPUB;	09:45
		adj process	1	USIMO
			EPO; JPO; DERWENT;	
	504		IBM_TDB	2002/00/24
·	501	scanner and machine adj process	USPAT;	2003/09/21
			US-PGPUB;	09:45
			EPO; JPO;	
		,	DERWENT;	
			IBM_TDB	
-	132	scanner and machine adj process and lan	USPAT;	2003/09/21
			US-PGPUB;	09:48
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	3864	scanner and panel and mark and	USPAT;	2003/09/21
		processing	US-PGPUB;	09:49
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
 -	6	scanner and panel and bad near mark and	USPAT;	2003/09/21
		processing	US-PGPUB;	09:50
1			EPO; JPO;	
			DERWENT;	
			IBM_TDB	

	3	bad adj mark near scanner and panel	USPAT;	2003/09/21
_	3	bau auj mark near scanner and paner	US-PGPUB;	09:50
			•	09:50
			EPO; JPO;	
			DERWENT;	
	23	made many accuracy and wavel	IBM_TDB	2002/00/04
-	23	mark near scanner and panel	USPAT;	2003/09/21
			US-PGPUB;	09:53
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	12	bad near mark and scanner and detect	USPAT;	2003/09/21
			US-PGPUB;	09:53
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	5	("4851902" "5323528" "5467913"	USPAT	2003/09/21
		"5657528" "5695667").PN.		09:55
-	4	("4578810" "4579455" "4668982"	USPAT	2003/09/21
		"4737845").PN.		09:56
-	3	("3349188" "3406258" "3202767").PN.	USPAT	2003/09/21
				10:34
-	1	3699263.URPN.	USPAT	2003/09/21
				10:35
_	3	("3699263" "3705268" "3876885").PN.	USPAT	2003/09/21
				10:35
-	1	3992592.URPN.	USPAT	2003/09/21
				10:36
-	2	PCB and assembly near line and scanner	USPAT;	2003/09/21
		and detect and bar adj code near reader	US-PGPUB;	10:39
			EPO; JPO;	10.00
			DERWENT;	
			IBM_TDB	
_	9	("3976973" "4115703" "4805175"	USPAT	2003/09/21
		"5144121" "5468949" "5818027"	Joi A.	10:38
		"5992750" "6094288" "6164546").PN.		. 3.00
_	8	PCB and assembly near line and bar adj	USPAT;	2003/09/21
		code near reader	US-PGPUB;	10:39
		lioni londo!	EPO; JPO;	10100
		.ú.	DERWENT;	
			IBM TDB	
	3	line adj scanner and apparatus and	_	2002/00/22
_	3	29/\$.ccis.	USPAT;	2003/09/22
		<u>ευφιστίοι</u>	US-PGPUB;	08:32
			EPO; JPO;	
			DERWENT;	
_	2	/!!ACACO72!! !!AOOE440!! !!E2040EC!!\ ===	IBM_TDB	0000100100
-	3	("4646073" "4805110" "5384956").PN.	USPAT	2003/09/22
				08:31
•	0	scanner and apparatus and 29/\$.ccls. and	USPAT;	2003/09/22
		WAN and LAn	US-PGPUB;	08:33
			EPO; JPO;	
			DERWENT;	
L	<u></u>		IBM_TDB	

_	245	scanner and apparatus and 29/\$.ccls.	HCDAT.	2003/09/22
-	245	scanner and apparatus and 29/\$.ccis.	USPAT;	08:50
			US-PGPUB;	00:50
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	17	("4175654" "5155888" "5157617"	USPAT	2003/09/22
1		"5283943" "5455409" "5515600"		08:36
		"5553376" "5557834" "5567927"	:	
		"5659440" "5713125" "5838574"		
		"5844593" "5980086" "6027019"		
		"6031242" "6045654").PN.		
	41	•	HEDAT	2002/00/22
-	41	("Re34615" "3337941" "3804270"	USPAT	2003/09/22
		"4144449" "4346293" "4351264"	:	08:42
		"4378134" "4383359" "4584047"		
		"4610083" "4615093" "5150423"		
1		"5157734" "5191693" "5195234"		
		"5213653" "5248362" "5249239"]	
		"5275657" "5278634" "5289625"		
		"5309223" "5311304" "5380099"		
		"5400497" "5415693" "5459794"		
		"5475919" "5488771" "5499756"		
		"5515600" "5547537" "5559727"		
		"5564188" "5592562" "5650081"		
		"5669970" "5708419" "5715594"		
		"5735040" "5788379").PN.		
-	68	scanner and apparatus and 29/\$.ccls. and	USPAT;	2003/09/22
		bar near code	US-PGPUB;	08:54
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	2	6049740.pn.	USPAT;	2003/09/22
	1		US-PGPUB;	10:10
			EPO; JPO;	
			DERWENT;	
			IBM TDB	
_	0	cad near scan and network and LAN and	USPAT;	2003/09/22
-		WAN	•	
		WAIT	US-PGPUB;	11:13
1			EPO; JPO;	
			DERWENT;	
1			IBM_TDB	
-	4246	scanner and network and LAN and WAN	USPAT;	2003/09/22
			US-PGPUB;	11:14
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	2213	scanner and network and LAN and WAN and	USPAT;	2003/09/22
		wireless	US-PGPUB;	11:14
			EPO; JPO;	
			DERWENT;	
L	J		IBM_TDB	

•	2	scanner and network and LAN and WAN and	USPAT;	2003/09/22
		wireless and 29/\$.ccls.	US-PGPUB;	11:15
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	0	20020083580.URPN.	USPAT	2003/09/22
				11:14
-	1	cad near scanner and network and LAN and	USPAT;	2003/09/22
		WAN and wireless	US-PGPUB;	11:16
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	1	cad near scanner and network and LAN and	USPAT;	2003/09/22
		WAN	US-PGPUB;	11:16
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	1	cad near scanner and network	USPAT;	2003/09/22
			US-PGPUB;	11:17
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	2	scancad and network	USPAT;	2003/09/22
			US-PGPUB;	11:17
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	2213	scanner and network and LAN and WAN and	USPAT;	2003/09/22
		wireless	US-PGPUB;	11:18
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	0	scanner and network and LAN and WAN and	USPAT;	2003/09/22
		wireless and PCB and mpunting near	US-PGPUB;	11:19
		apparatus	EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	0	scanner and network and LAN and WAN and	USPAT;	2003/09/22
	:	wireless and PCB and mounting near	US-PGPUB;	11:19
		apparatus	EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	44	scanner and network and LAN and WAN and	USPAT;	2003/09/22
		wireless and PCB	US-PGPUB;	11:19
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	